

WEEK 30-31 PHOTOS (6)



Controls for new Snowmelt System-6 miles of pipes under the driveway



Snowmelt driveway with new bus stop and turnaround



Entryway to Office in Building A



New Retaining Wall and dual-purpose shed housing boilers in back and trash/recycling dumpsters in front



Sculpted concrete barrier wall at entrance



New Staircases to lower buildings and "The Great Wall of Snowmass"